ABC COMPANIES
Exclusive U.S. VANHOOL Distributor

TECH TIPS
#1203

COACH MODEL :	T 2140, T2145, C2045
DATE :	1/04/2012
SUBJECT :	Rear Undercarriage Cross Members

CROSS MEMBER INSPECTION

It is very important to regularly inspect the rear undercarriage cross members. Coaches used in rough environment and rough roads can cause these parts to crack. Coaches operated with these cross members broken or missing can cause frame damage in the engine and tag axle areas. The following pictures indicate where these cross members are located.

Tag Axle Cross Member



Engine Cross Member



Please refer to Van Hool Service Bulletin SB-1184 for details and VIN numbers for appropriate replacement cross members.
Contact your nearest ABC service location, parts counter, or Customer Care at 877-427-7278 for availability and ordering information.