QUALITIES THAT MAKE THE DIFFERENCE

# Service Bulletin No.1029

| | |
|---|---|
| MODEL | : **T 900 Series** |
| TYPE | : **Service information** |
| MANUAL & SECTION | : **Refer to the Service Procedure in this Bulletin** |
| DATE | : **January 31st, 2000** |
| SUBJECT | : **M377 Maintenance Manual, volume 1, revision C** |
| CONDITIONS | : **-** |

**DESCRIPTION** : The latest revision of Van Hool manual M 377 Volume 1 has been released for distribution to end-users. Refer to the filing instructions in the Service Procedure and use the revised sections accompanying this Bulletin to keep your T-900 reference book up-to-date.

Service Bulletins are issued to supplement or supersede information in the Van Hool manuals. Note Service Bulletin number, date and subject on the register at the end of the relevant chapter(s). File Service Bulletin separately for future reference.

**SERVICE PROCEDURE**

**To update manual M377 : T-900/40 & T-900/45 Maintenance Manual, Volume 1**

| REPLACE OBSOLETE... | BY NEW... |
|---|---|
| • Cover label (revision B), Date 02/98<br>• Table of contents<br>chapter 3, Date 02/98<br>• Section 3.1, Date 02/98<br>• Special service tools<br>chapter 3, Date 11/96<br>• Section 4.1, Date 02/98<br>• Section 4.4, Date 04/97<br>• Special service tools<br>chapter 4, Date 11/96<br>• Section 5.8, Date 02/98<br>• Table of contents<br>chapter 7, Date 09/96<br>• Section 7.2, Date 05/97<br>• Section 12.1, Date 02/98<br>• Section 12.3, Date 09/96 | • Cover label (revision C), Date 12/98<br>• Table of contents<br>chapter 3, Date 12/98<br>• Section 3.1, Date 12/98<br>• Special service tools<br>chapter 3, Date 12/98<br>• Section 4.1, Date 12/98<br>• Section 4.4, Date 12/98<br>• Special service tools<br>chapter 4, Date 12/98<br>• Section 5.8, Date 12/98<br>• Table of contents<br>chapter 7, Date 12/98<br>• Section 7.2, Date 09/98<br>• Section 12.1, Date 09/98<br>• Section 12.3, Date 12/98 |

*Procedure complete*