SERVICE INFORMATION:

- **Vehicle Identification Numbers (VIN) of coaches without ABS, on which 3.9 ft (1200mm) brake hoses must be replaced.**

Model	Engine	Brakes	VIN
T900/ S945	Cummins	D3	27691 → 27695 28480 → 28485 28572 → 28600 29013 → 29154 except 29072 29301 → 29454 29701 → 29719
T2140	Cummins	D3	40000 → 40049
	Detroit Diesel		40501 → 40514
T2145	Cummins	D3	43000 → 43051
	Detroit Diesel		43501 → 43576

- **Vehicle Identification Numbers (VIN) of coaches equipped with ABS, on which 2.6 ft (800 mm) brake hoses must be replaced.**

Model	Engine	Brakes	VIN
T900/ S945	Cummins	D3 + ABS	29072 29155 → 29200 29455 → 29500 29720 → 29763 29901 → 29986 42001 → 42037 42101 → 42150
T2140	Cummins	D3 + ABS	40050 → 40147
	Detroit Diesel		40515 → 40610
T2145	Cummins	D3 + ABS	43052 → 43499 44001 → 44027
	Detroit Diesel		43577 → 43920 44501 → 44507 44513 → 44514
C2045	Cummins	D3+ ABS	45001 → 45005
	Detroit Diesel		45501 → 45504

- Service Bulletins are issued to supplement or supersede information in the Van Hool manuals. Note Service Bulletin number, date and subject on the register at the end of the relevant chapter(s). File Service Bulletin separately for future reference.