

COACH MODEL : VanHool coach models with Proheat installed

DATE : 1/12/2015

SUBJECT : Distorted combustion tube insert, may or may not log fault code

When inspecting a Proheat combustion heater unit for maintenance, or a no start condition with or without fault codes, pay close attention to the combustion tube insert.

If it is out of round like this one in this picture, the Proheat combustion heater may fire then shut off with no fault codes logged, or may log a start Diagnostic code #1.

If you find your the combustion tube is out of round, replace combustion tube.

